



4121 North Highway 81 Bypass
 Enid, OK 73701
 Phone: (580) 237-2304
 www.pkequipment.com



SERVICE INVOICE

Invoice To Account No:

Deliver To: ***** PROFORMA INVOICE *****

Internal Used Stock No. 135435

 Bus Phone:
 Prv Phone:

Internal Used Stock No. 135435

 Bus Phone:
 Prv Phone:

Invoice Number:
Invoice Date: 04/16/2015
Location: 2
Work Order Number: 411101
Payment Type: Account

Page: 1 of 5

Make/Model: 2003 JOHN DEERE 956 MOCO
Meter Reading:
Serial Number: E00956T174137
Equipment Number: 50585W

Gen- Internal

COMPLAINT:
 SERVICE REQUEST: INSPECT MAKE AUCTION READY

 CAUSE:

 CORRECTION:
 SERVICE QUOTE:



SERVICE PERFORMED: Looked over for auction.

Labor Subtotal: \$69.59

OL&M Charges:

<u>Vendor Name</u>	<u>Description</u>	<u>Value</u>
AUTO SPECIALTIES	EXT WASH, CLEAN TOP DECK	\$150.00

OL&M Subtotal: \$150.00

Labor: \$69.59 Parts: \$0.00 OL&M: \$150.00 Misc: \$0.00 Sub-Total: \$219.59

Gen1- Internal

COMPLAINT:
 SERVICE REQUEST: DRIVE BELT (LOWER)

 CAUSE:



4121 North Highway 81 Bypass
 Enid, OK 73701
 Phone: (580) 237-2304
 www.pkequipment.com



SERVICE INVOICE

Invoice To Account No:

Deliver To: ***** PROFORMA INVOICE *****

Internal Used Stock No. 135435

 Bus Phone:
 Prv Phone:

Internal Used Stock No. 135435

 Bus Phone:
 Prv Phone:

Invoice Number:
Invoice Date: 04/16/2015
Location: 2
Work Order Number: 411101
Payment Type: Account

Page: 2 of 5

Make/Model: 2003 JOHN DEERE 956 MOCO
Meter Reading:
Serial Number: E00956T174137
Equipment Number: 50585W

Gen1- Internal

CORRECTION;
 SERVICE QUOTE:

SERVICE PERFORMED: Went out and found the unit. Checked the unit over and found the things that needed to be replaced. Started to replace the lower drive belt. The I-bolt broke that holds tension on the belt. Ordered a new bolt. Removed the inner shield. Cleaned the trash out from around the old belt. Was able to remove the old belt. Installed the new belt. Got the new I-bolt and installed it. Adjusted the belt to spec. checked the operation. Took all tools and put them away.

Labor Subtotal: \$512.94

Parts / Misc Items:

<u>PartNumber</u>	<u>Description</u>	<u>Quantity</u>	<u>Unit Net</u>	<u>Value</u>	<u>Taxed Ind</u>
14M7274	Nut	2.00	0.62	\$1.24	N
24M7178	Washer	1.00	1.01	\$1.01	N
E83777	V-Belt	1.00	155.91	\$155.91	N
H114738	Eyebolt	1.00	14.17	\$14.17	N

Parts Subtotal: \$172.33

<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>Unit Net</u>	<u>Value</u>	<u>Taxed Ind</u>
3750	FREIGHT	1.00	10.00	\$10.00	N

Misc Items Subtotal: \$10.00

Labor: \$512.94 Parts: \$172.33 OL&M: \$0.00 Misc: \$10.00 Sub-Total: \$695.27



4121 North Highway 81 Bypass
 Enid, OK 73701
 Phone: (580) 237-2304
 www.pkequipment.com



SERVICE INVOICE

Invoice To Account No:	Deliver To: *** PROFORMA INVOICE ***	
Internal Used Stock No. 135435	Internal Used Stock No. 135435	Invoice Number: Invoice Date: 04/16/2015 Location: 2 Work Order Number: 411101 Payment Type: Account Page: 3 of 5
Bus Phone:	Bus Phone:	Make/Model: 2003 JOHN DEERE 956 MOCO Meter Reading: Serial Number: E00956T174137 Equipment Number: 50585W
Prv Phone:	Prv Phone:	

Gen2- Internal

COMPLAINT:
 SERVICE REQUEST: RH SKID PLATE MISSING PIN



CAUSE:

CORRECTION:
 SERVICE QUOTE:

SERVICE PERFORMED: Installed new pins on the right hand skid plate.

Parts / Misc Items:

<u>PartNumber</u>	<u>Description</u>	<u>Quantity</u>	<u>Unit Net</u>	<u>Value</u>	<u>Taxed Ind</u>
11M7015	Cotter Pin	2.00	0.24	\$0.48	N
M72529	Pin Fastener	2.00	6.40	\$12.80	N

Parts Subtotal: \$13.28

Labor: \$0.00 Parts: \$13.28 OL&M: \$0.00 Misc: \$0.00 Sub-Total: \$13.28

Gen3- Internal



4121 North Highway 81 Bypass
 Enid, OK 73701
 Phone: (580) 237-2304
 www.pkequipment.com



SERVICE INVOICE

Invoice To Account No:

Deliver To: ***** PROFORMA INVOICE *****

Internal Used Stock No. 135435

 Bus Phone:
 Prv Phone:

Internal Used Stock No. 135435

 Bus Phone:
 Prv Phone:

Invoice Number:
Invoice Date: 04/16/2015
Location: 2
Work Order Number: 411101
Payment Type: Account

Page: 4 of 5

Make/Model: 2003 JOHN DEERE 956 MOCO
Meter Reading:
Serial Number: E00956T174137
Equipment Number: 50585W

Gen3- Internal

COMPLAINT:
 SERVICE REQUEST: LH FLASHER

CAUSE:

CORRECTION:
 SERVICE QUOTE:

SERVICE PERFORMED: Replaced the left warning light.

Parts / Misc Items:

<u>PartNumber</u>	<u>Description</u>	<u>Quantity</u>	<u>Unit Net</u>	<u>Value</u>	<u>Taxed Ind</u>
AH164497	Lamp	1.00	24.15	\$24.15	N

Parts Subtotal:

\$24.15

Labor: \$0.00 Parts: \$24.15 OL&M: \$0.00 Misc: \$0.00 Sub-Total: \$24.15

Customer PO No:
Tax Exempt No: DummyExemptNo
Advisor: Timothy Krienke

Labor: \$582.53
Parts: \$209.76
OL&M: \$150.00
Misc: \$10.00
Sales Tax: \$0.00
Grand Total: \$952.29



4121 North Highway 81 Bypass
 Enid, OK 73701
 Phone: (580) 237-2304
 www.pkequipment.com



SERVICE INVOICE

Invoice To Account No:

Deliver To: ***** PROFORMA INVOICE *****

Internal Used Stock No. 135435
Bus Phone:
Prv Phone:

Internal Used Stock No. 135435
Bus Phone:
Prv Phone:

Invoice Number:	
Invoice Date	04/16/2015
Location:	2
Work Order Number:	411101
Payment Type:	Account
Page:	5 of 5

Make/Model:	2003 JOHN DEERE 956 MOCO
Meter Reading:	
Serial Number:	E00956T174137
Equipment Number:	50585W



TERMS AND CONDITIONS

Received by:

Date: