

**Rod Miller**


Part of Sec's 26 & 35, T-120, R-30

REVISION: _____ DATE _____, 20____

CHECKED BY: DSH

VERTICAL DATUM:
N/A

3: Subsurface buildings, improvements and/or Environmental issues may exist on site that we were not made aware of and therefore were not examined or considered during the process of this survey.



- ☐ Set 1/2 Inch by 14 Inch Iron Pipe with Plastic Cap Inscribed with License No. 43808
- ☒ Found Monumentation
- ☐ Set PK Nail
- ☒ Government Section Corner