



4121 North Highway 81 Bypass
 Enid, OK 73701
 Phone: (580) 237-2304
 www.pkequipment.com



JOHN DEERE

Invoice To Account No.: 151

Deliver To:

*** DOCUMENT COPY ***

SERVICE INVOICE

WARRANTY CUSTOMER - P&K EQUIPMENT Bus Phone: Prv Phone:	P&K EQUIPMENT, INC - ENID 4121 N. HWY 81 BYPASS ENID OK 73701 Bus Phone: 580-237-2304 Prv Phone: 800-375-4440	Invoice Number: 1455899 Invoice Date: 1/31/2014 Location: 2 Work Order Number: 318578 Payment Type: Account Page: 1 of 7
--	---	--

Make/Model:	JOHN DEERE JD 8360R
Meter Reading:	712
Serial Number:	1RW8360RPBD043281
Equipment Number:	104371

Gen- Warranty

COMPLAINT:

SERVICE REQUEST: FAULT CODES; PTI 524232.02, PARK BRAKE PRESSURE SENSOR CIRCUIT FAULT, AND PTI 524228.11, PARK SUMP BLOCK VALVE FAULT,

CAUSE:

CORRECTION:

\$10,647.00



4121 North Highway 81 Bypass
 Enid, OK 73701
 Phone: (580) 237-2304
 www.pkequipment.com



JOHN DEERE

Invoice To Account No.: 151

Deliver To:

*** DOCUMENT COPY ***

SERVICE INVOICE

WARRANTY CUSTOMER - P&K EQUIPMENT	P&K EQUIPMENT, INC - ENID 4121 N. HWY 81 BYPASS ENID OK 73701	Invoice Number: 1455899
		Invoice Date: 1/31/2014
		Location: 2
Bus Phone:	Bus Phone: 580-237-2304	Work Order Number: 318578
Prv Phone:	Prv Phone: 800-375-4440	Payment Type: Account
		Page: 2 of 7

Make/Model:	JOHN DEERE JD 8360R
Meter Reading:	712
Serial Number:	1RW8360RPBD043281
Equipment Number:	104371

Gen- Warranty

SERVICE REQUEST: FAULT CODES; PT1 524232.02, PARK BRAKE PRESSURE SENSOR CIRCUIT FAULT, AND PT1 524228.11, PARK SUMP BLOCK VALVE FAULT,

DIAGNOSIS:

SERVICE QUOTE:

SERVICE PERFORMED: TRACTOR CAME INTO SHOP WITH ACTIVE CODES. ACU 001745.04 - PT1 524228.11 & 524232.02 - SFA 522288.06 - XSC 523329.14, 1044.07.

CHECKED DIAGNOSTICS PER CODE #'S. FILED DTAC CASE FOR ASSISTANCE DUE TO CHECKS ALL PROVED GOOD. REPLACED SENSOR AT PARK BRAKE. REPLACED PARK BRAKE SOLENOID. NO CHANGE INT THE PT1 CODES. CHECKED & COMPAIRED READING TO ANOTHER TRACTOR ON OUR LOT. FOUND PT1 13 WAS LOW. DID EXTENSIVE PRESSURE TEST & FOUND PARK BRAKE PRESSURE TO BE LOW. CHECKED ACU - SFA & XSC CODES THEY WERE CURED BY REPLACING THE LEFT HAND REVERSER. R & R STEERING COLUMN, REPLACED CONTROLLER. UPDATED SOFTWARE AT ALL CONTROLLERS FOR TRACTOR.

SPLIT TRACTOR TO TRY & LOCATE PARK BRAKE LEAK. REMOVED TRANSMISSION (HAD TO MODIFY BRACKETS & STAND TO ACCOMODATE TRANSMISSION TO ENGINE STAND) (HAD TO LOCATE, ASSEMBLE & CLEAN SPLITTING STANDS FOR THIS SPLIT). ATTACHED THE TRANSMISSION TO THE STAND. REMOVED THE REAR VALVE HOUSING, REMOVED REAR HOUSINGS. DISASSEMBLED PARK BRAKE PISTON. I FOUND NOTHING THAT WAS BENT, BROKEN OR WORN. HOWEVER THE MACHINE SURFACE OF THE REAR HOUSING WAS NOT A FLAT PLANED SURFACE. ADVISED DTAC, THEY RECOMMENDED TO REPLACE REAR VALVE HOUSING. WHEN NEW HOUSING ARRIVED IT WAS MACHINED THE SAME WAY. NOTIFIED DTAC, THEY GOT WITH ENGINEERING & SAID THAT WAS THE PROCESS USED TO MILL THE HOUSING. GOT WITH DTAC & SCOTT. WE DECIDED TO ALSO ORDER THE REAR TRANSMISSION HOUSING. REBUILT THE PARK BRAKE. REPLACED SEALING RINGS AT THE DRIVE SHFATS THROUGH THE REAR HOUSING. PUT REAR HOUSING ON, WHEN ATTEMPTING TO SET REAR VALVE HOUSING ON, I NOTICED SOMETHING IN THE TRANSMISSION THAT STOOD OUT. USED A FLEXIBLE MAGNET & DREW OUT A BOLT THAT HAD BEEN FLOATING IN THERE FOR SOME TIME PER THE DAMAGE TO THE BOLT. REOPENED DTAC WITH BOLT SPEC SO THEY COULD POSSIBLY TELL WHERE THIS SIZE BOLT WAS USED. THIS SIZE IS NOT USED ANYWHERE IN THE TRANSMISSION. DISASSEMBLED TRANSMISSION. FOUND ONE BRIGHT SILVER BOLT. CHECKED & IT APPEARS THAT IT WAS THE RIGHT SIZE FOR WHERE IT WAS, HOWEVER IT DID NOT MATCH THE ONE THAT SHOULD BE THERE. IT IS BELIEVED THAT THERE WAS A MIX UP ON BOLTS IN THIS FLANGE & THIS BOLT FELL INTO THE TRANSMISSION DURING THE PROCESS. REASSEMBLED TRANSMISSION, PUT TRANSMISSION IN TRACTOR. REPLACED BROKEN SOLENOID AT LEFT SIDE OF TRANSMISSION. REPLACED ONE WIRE CONNECTOR FOR SOLENOID, IT WAS DAMAGED DURING THE SEPARATION. FASTENED & SECURED ALL LINES, DRIVE SHAFTS. TORQUED MOUNTING HARDWARE.



4121 North Highway 81 Bypass
 Enid, OK 73701
 Phone: (580) 237-2304
 www.pkequipment.com



JOHN DEERE

Invoice To Account No.: 151

Deliver To:

*** DOCUMENT COPY ***

SERVICE INVOICE

WARRANTY CUSTOMER - P&K EQUIPMENT	P&K EQUIPMENT, INC - ENID 4121 N. HWY 81 BYPASS ENID OK 73701	Invoice Number:	1455899
		Invoice Date:	1/31/2014
Bus Phone: Prv Phone:	Bus Phone: 580-237-2304 Prv Phone: 800-375-4440	Location:	2
		Work Order Number:	318578
		Payment Type:	Account
		Page:	3 of 7

Make/Model:	JOHN DEERE JD 8360R
Meter Reading:	712
Serial Number:	1RW8360RPBD043281
Equipment Number:	104371

STARTED TRACTOR, PT1 630.13 WOULD LOCK THE MACHINE OUT. TESTED & HAD NOT SYSTEM 2 PRESSURE. CHECKED & HAD NO LUBE PRESSURE. AFTER SEVERAL TESTS & CHECKS & SEVERAL CALLS TO & FROM DTAC. I FOUND THAT THE C2 SOLENOID CLUTCH HAD A STUCK VALVE. REMOVED VALVE, CLEANED BORE & REASSEMBLED. STARTED TRACTOR, CODE CLEARED & TRANSMISSION CALIBRATED. CHECKED PRESSURES. CHECKED READINGS AT PTI ADDRESSES FOR PARK PRESSURE, SYSTEM PRESSURE, LUBE PRESSURE, ALL ARE IN SPEC. DROVE TRACTOR & CHECKED, IN & OUT OF GEAR. PARK TO F-N-R. DROVE TRACTOR, NO CODES SET. I DROVE & CHECKED TRACTOR ON A FRIDAY AFTERNOON & THEN ON & ON MONDAY. ALL IS GOOD NOW.

TRACTOR WOULD NOT START GOOD ON INITIAL CHECKS. REPLACED BATTERIES DUE TO QUESTIONABLE VOLTAGE.

REPLACED TRANSMISSION OIL & FILTERS. 46 GALLONS OF BULK HYD FLUID.

Part Number	Description	Quantity	Unit Net	Value	Taxed Inc
07480	GRIND DIS	3.00	1.33	\$3.99	N
14M7303	Flange Nut	1.00	0.34	\$0.34	N
15H197	Elbow Fitting	1.00	3.94	\$3.94	N
19M7789	Screw	1.00	0.77	\$0.77	N
19M7800	Screw	1.00	1.06	\$1.06	N
2490	SPLIT R/O	1.00	-10,236.00	(\$10,236.00)	N
24H1122	Washer	3.00	0.40	\$1.20	N
24M7024	Washer	2.00	0.64	\$1.28	N
3750	FREIGHT	621.00	2.50	\$1,552.50	N
40M7043	Snap Ring	1.00	4.93	\$4.93	N
51M7045	O-Ring	2.00	1.64	\$3.28	N
51M7121	O-Ring	2.00	0.77	\$1.54	N
57M7689	Fuse	1.00	0.91	\$0.91	N
57M8560	Elec. Connector Terminal	2.00	0.30	\$0.60	N
57M8566	Elec. Connector Seal	2.00	0.07	\$0.14	N



4121 North Highway 81 Bypass
 Enid, OK 73701
 Phone: (580) 237-2304
 www.pkequipment.com



JOHN DEERE

Invoice To Account No.: 151

Deliver To:

*** DOCUMENT COPY ***

SERVICE INVOICE

WARRANTY CUSTOMER - P&K
 EQUIPMENT

Bus Phone:
 Prv Phone:

P&K EQUIPMENT, INC - ENID
 4121 N. HWY 81 BYPASS
 ENID OK 73701

Bus Phone: 580-237-2304
 Prv Phone: 800-375-4440

Invoice Number: **1455899**
 Invoice Date: 1/31/2014
 Location: 2
 Work Order Number: 318578
 Payment Type: Account
 Page: 4 of 7

Make/Model: JOHN DEERE JD 8360R
 Meter Reading: 712
 Serial Number: 1RW8360RPBD043281
 Equipment Number: 104371

Gen- Warranty

57M8924	Elec. Connector Housing	1.00	2.22	\$2.22	N
B2762R	O-Ring	9.00	1.93	\$17.37	N
F3171R	O-Ring	6.00	1.86	\$11.16	N
H140149	Clip	5.00	0.88	\$4.40	N
P50631	O-Ring	2.00	2.86	\$5.72	N
PM37509	Primer	3.00	14.39	\$43.17	N
PM38657	Sealant	3.00	17.03	\$51.09	N
R112857	O-RING	2.00	2.48	\$4.96	N
R115233	Shaft	1.00	53.08	\$53.08	N
R119207	SEAL	2.00	8.21	\$16.42	N
R134	FREON	7.00	4.29	\$30.03	N
R160628	Compression Spring	1.00	2.86	\$2.86	N
R161101	Compression Spring	1.00	3.29	\$3.29	N
R171705	Ring	5.00	6.30	\$31.50	N
R183410	O-Ring	1.00	0.92	\$0.92	N
R195528	Ring	2.00	3.56	\$7.12	N
R201255	Bushing	1.00	19.91	\$19.91	N
R205587	Piston Ring	8.00	6.53	\$52.24	N
R205591	Disk Spring	3.00	60.10	\$180.30	N
R211099	Packing	1.00	5.35	\$5.35	N
R212714	Pin	1.00	2.23	\$2.23	N
R214783	Compression Spring	1.00	6.23	\$6.23	N
R218285	Pin	1.00	7.31	\$7.31	N
R218648	Spool Valve	1.00	24.55	\$24.55	N



4121 North Highway 81 Bypass
 Enid, OK 73701
 Phone: (580) 237-2304
 www.pkequipment.com



Invoice To Account No.: 151

Deliver To:

*** DOCUMENT COPY ***

SERVICE INVOICE

WARRANTY CUSTOMER - P&K EQUIPMENT	P&K EQUIPMENT, INC - ENID 4121 N. HWY 81 BYPASS ENID OK 73701	Invoice Number:	1455899
		Invoice Date:	1/31/2014
Bus Phone: Prv Phone:	Bus Phone: 580-237-2304 Prv Phone: 800-375-4440	Location:	2
		Work Order Number:	318578
		Payment Type:	Account
		Page:	5 of 7

Make/Model:	JOHN DEERE JD 8360R
Meter Reading:	712
Serial Number:	1RW8360RPBD043281
Equipment Number:	104371

Gen- Warranty

Part Number	Description	Qty	Unit Price	Total Price	Warranty
R220147	Sealing Ring	1.00	1.49	\$1.49	N
R224235	Washer	2.00	0.41	\$0.82	N
R225459	Clutch Plate	6.00	15.94	\$95.64	N
R225461	Housing	1.00	198.64	\$198.64	N
R225462	Piston	1.00	131.16	\$131.16	N
R225620	Spool Valve	1.00	31.86	\$31.86	N
R226598	Packing	1.00	6.95	\$6.95	N
R242526	Cap Screw	23.00	6.28	\$144.44	N
R246004	Ball Bearing	1.00	19.40	\$19.40	N
R249577	Plate	1.00	104.93	\$104.93	N
R251181	Thrust Washer	1.00	2.69	\$2.69	N
R260475	Valve Spool	1.00	13.31	\$13.31	N
R264379	Spool Valve	1.00	33.36	\$33.36	N
R27166	O-Ring	1.00	1.03	\$1.03	N
R313206	Gasket	1.00	32.32	\$32.32	N
R539324	Gasket	1.00	19.10	\$19.10	N
R56465	O-Ring	1.00	0.84	\$0.84	N
R86638	Shim	2.00	0.96	\$1.92	N
R99039	O-Ring	1.00	2.69	\$2.69	N
RE179984	Pressure Sensor	1.00	205.44	\$205.44	N
RE190805	Diagnostic Coupling	1.00	12.86	\$12.86	N
RE210857	OIL FILTER	2.00	69.98	\$139.96	N
RE211156	Solenoid Valve	1.00	152.54	\$152.54	N
RE212444	Valve Seat	1.00	131.16	\$131.16	N



4121 North Highway 81 Bypass
 Enid, OK 73701
 Phone: (580) 237-2304
 www.pkequipment.com



JOHN DEERE

Invoice To Account No.: 151

Deliver To:

*** DOCUMENT COPY ***

SERVICE INVOICE

WARRANTY CUSTOMER - P&K EQUIPMENT	P&K EQUIPMENT, INC - ENID 4121 N. HWY 81 BYPASS ENID OK 73701	Invoice Number:	1455899
		Invoice Date:	1/31/2014
		Location:	2
		Work Order Number:	318578
		Payment Type:	Account
Bus Phone:	Bus Phone: 580-237-2304	Page:	6 of 7
Prv Phone:	Prv Phone: 800-375-4440		

Make/Model:	JOHN DEERE JD 8360R
Meter Reading:	712
Serial Number:	1RW8360RPBD043281
Equipment Number:	104371

Gen- Warranty

RE212709	Control Valve	2.00	176.15	\$352.30	N
RE217077	Trans Oil Pressure Sensor	1.00	77.44	\$77.44	N
RE236921	Compression Spring	1.00	7.72	\$7.72	N
RE244397	Solenoid Valve	2.00	93.70	\$187.40	N
RE246597	Cover	1.00	1,649.00	\$1,649.00	N
RE246760	Manifold	1.00	1,755.94	\$1,755.94	N
RE272647	Trans Oil Pressure Sensor	1.00	107.92	\$107.92	N
RE294021	Clutch Disk	6.00	30.59	\$183.54	N
RE306839	Module	1.00	789.82	\$789.82	N
RE32442	Seal	1.00	22.39	\$22.39	N
RE40413	Seal	1.00	19.80	\$19.80	N
RE46684	Fitting Plug	1.00	3.73	\$3.73	N
TY22028	HY-Gard	214.00	2.76	\$590.64	N
TY25624	GREEN SPRA	2.00	8.54	\$17.08	N
TY25879	DRY CHARGE	2.00	169.64	\$339.28	N
TY26101	Cleaning Solvent	2.00	4.43	\$8.86	N
TY26575	COOL-GARD	1.00	13.72	\$13.72	N
TY26633	Degreasing Solvent	15.00	3.16	\$47.40	N
TY5021	TAPE	1.00	2.75	\$2.75	N



4121 North Highway 81 Bypass
 Enid, OK 73701
 Phone: (580) 237-2304
 www.pkequipment.com



JOHN DEERE

Invoice To Account No.: 151

Deliver To: ***** DOCUMENT COPY *****

SERVICE INVOICE

WARRANTY CUSTOMER - P&K EQUIPMENT Bus Phone: Prv Phone:	P&K EQUIPMENT, INC - ENID 4121 N. HWY 81 BYPASS ENID OK 73701 Bus Phone: 580-237-2304 Prv Phone: 800-375-4440	Invoice Number: 1455899 Invoice Date: 1/31/2014 Location: 2 Work Order Number: 318578 Payment Type: Account Page: 7 of 7
--	---	--

Make/Model:	JOHN DEERE JD 8360R
Meter Reading:	712
Serial Number:	1RW8360RPBD043281
Equipment Number:	104371

Gen- Warranty U44496	O-RING	2.00	1.90	\$3.80	N
Labor: \$10,647.00		Parts: \$8,272.49	OL&M: \$0.00	Misc: (\$8,683.50)	Sub-Total: \$10,235.99

Customer PO No:	
Tax Exempt No:	EXEMPT
Advisor:	Timothy Krienke

Labor:	\$10,647.00
Parts:	\$8,272.49
OL&M:	\$0.00
Misc:	(\$8,683.50)
Sales Tax:	\$0.00
Total:	\$10,235.99

TERMS AND CONDITIONS

Farm Plan transactions are subject to the terms of Farm Plan.
 All open accounts are payable by the 10th of the month following the date of purchase. Accounts not paid by the 10th of the month following purchase are subject to interest charges of 1.5% per month, which is an 18% annual rate. Accounts which are not paid by the 10th of the month are subject to closure and collection procedures. Parties agree that jurisdiction and venue of any action brought to enforce or collect this account shall properly lie in Kingfisher County, State of Oklahoma. In the event that P&K Equipment, Inc. must employ an attorney to enforce or collect this amount, they shall be entitled to recover reasonable attorney fees and expenses incurred therein.
 Purchaser certifies under penalty of perjury that he is engaged in farming or ranching and farm machinery & farm equipment parts described hereon will be used only in his farming or ranching operation.

Received by: Date:



4121 North Highway 81 Bypass
 Enid, OK 73701
 Phone: (580) 237-2304
 www.pkequipment.com



JOHN DEERE

Invoice To Account No.:

Deliver To:

*** DOCUMENT COPY ***

SERVICE INVOICE

Internal Used Stock No. 196100	Internal Used Stock No. 196100	Invoice Number: 1455937
		Invoice Date: 1/31/2014
		Location: 2
		Work Order Number: 318578
		Payment Type: Account
Bus Phone:	Bus Phone:	Page: 1 of 4
Prv Phone:	Prv Phone:	

Make/Model:	JOHN DEERE JD 8360R
Meter Reading:	712
Serial Number:	1RW8360RPBD043281
Equipment Number:	104371

Gen1- Internal
 COMPLAINT:
 SERVICE REQUEST:steering stop

CAUSE:

CORRECTION:
 SERVICE REQUEST:steering stop

\$680.00

DIAGNOSIS:

SERVICE QUOTE:

SERVICE PERFORMED: RIGHT HAND STEERING STOP WAS GONE, BOLT THAT HOLDS STOP IN PLACE HAD BROKE.
 REMOVED BROKEN BOLT. REPLACED STEERING STOP.

EXT WASH, INT COMPLETE, WAX

Part Number	Description	Quantity	Unit Nett	Value	Taxed Ind
19M7788	Screw	1.00	1.12	\$1.12	N
24H1288	Washer	1.00	0.63	\$0.63	N
3750	FREIGHT	3.00	2.50	\$7.50	N
R193545	Tool	1.00	39.84	\$39.84	N
TY26633	Degreasing Solvent	2.00	3.29	\$6.58	N
Labor: \$405.00		Parts: \$48.17		OL&M: \$275.00	
		Misc: \$7.50		Sub-Total: \$735.67	

GEN2- Internal
 COMPLAINT:
 SERVICE REQUEST: FAULT CODES; PTI 524232.02, PARK BRAKE PRESSURE SENSOR CIRCUIT FAULT, AND PTI 524228.11, PARK SUMP BLOCK VALVE FAULT,

CAUSE:



4121 North Highway 81 Bypass
 Enid, OK 73701
 Phone: (580) 237-2304
 www.pkequipment.com



JOHN DEERE

Invoice To Account No.:

Deliver To:

*** DOCUMENT COPY ***

SERVICE INVOICE

Internal Used Stock No. 196100

 Bus Phone:
 Prv Phone:

Internal Used Stock No. 196100

 Bus Phone:
 Prv Phone:

Invoice Number: **1455937**
 Invoice Date: 1/31/2014
 Location: 2
 Work Order Number: 318578
 Payment Type: Account

 Page: 2 of 4

Make/Model: JOHN DEERE JD 8360R
 Meter Reading: 712
 Serial Number: 1RW8360RPBD043281
 Equipment Number: 104371

GEN2- Internal

CORRECTION:



4121 North Highway 81 Bypass
 Enid, OK 73701
 Phone: (580) 237-2304
 www.pkequipment.com



Invoice To Account No.:	Deliver To:	*** DOCUMENT COPY ***	SERVICE INVOICE
Internal Used Stock No. 196100	Internal Used Stock No. 196100	Invoice Number:	1455937
		Invoice Date:	1/31/2014
		Location:	2
		Work Order Number:	318578
		Payment Type:	Account
Bus Phone:	Bus Phone:	Page:	3 of 4
Prv Phone:	Prv Phone:		

Make/Model:	JOHN DEERE JD 8360R
Meter Reading:	712
Serial Number:	1RW8360RPBD043281
Equipment Number:	104371

GEN2- Internal
 SERVICE REQUEST: FAULT CODES; PT1 524232.02, PARK BRAKE PRESSURE SENSOR CIRCUIT FAULT, AND PT1 524228.11, PARK SUMP BLOCK VALVE FAULT,

DIAGNOSIS:

SERVICE QUOTE:

SERVICE PERFORMED: TRACTOR CAME INTO SHOP WITH ACTIVE CODES. ACU 001745.04 - PT1 524228.11 & 524232.02 - SFA 522288.06 - XSC 523329.14, 1044.07.

CHECKED DIAGNOSTICS PER CODE #'S. FILED DTAC CASE FOR ASSISTANCE DUE TO CHECKS ALL PROVED GOOD. REPLACED SENSOR AT PARK BRAKE. REPLACED PARK BRAKE SOLENOID. NO CHANGE INT THE PT1 CODES. CHECKED & COMPAIRED READING TO ANOTHER TRACTOR ON OUR LOT. FOUND PT1 13 WAS LOW. DID EXTENSIVE PRESSURE TEST & FOUND PARK BRAKE PRESSURE TO BE LOW. CHECKED ACU - SFA & XSC CODES THEY WERE CURED BY REPLACING THE LEFT HAND REVERSER. R & R STEERING COLUMN, REPLACED CONTROLLER. UPDATED SOFTWARE AT ALL CONTROLLERS FOR TRACTOR.

SPLIT TRACTOR TO TRY & LOCATE PARK BRAKE LEAK. REMOVED TRANSMISSION (HAD TO MODIFY BRACKETS & STAND TO ACCOMODATE TRANSMISSION TO ENGINE STAND) (HAD TO LOCATE, ASSEMBLE & CLEAN SPLITTING STANDS FOR THIS SPLIT). ATTACHED THE TRANSMISSION TO THE STAND. REMOVED THE REAR VALVE HOUSING, REMOVED REAR HOUSINGS. DISASSEMBLED PARK BRAKE PISTON. I FOUND NOTHING THAT WAS BENT, BROKEN OR WORN. HOWEVER THE MACHINE SURFACE OF THE REAR HOUSING WAS NOT A FLAT PLANED SURFACE. ADVISED DTAC, THEY RECOMMENDED TO REPLACE REAR VALVE HOUSING. WHEN NEW HOUSING ARRIVED IT WAS MACHINED THE SAME WAY. NOTIFIED DTAC, THEY GOT WITH ENGINEERING & SAID THAT WAS THE PROCESS USED TO MILL THE HOUSING. GOT WITH DTAC & SCOTT. WE DECIDED TO ALSO ORDER THE REAR TRANSMISSION HOUSING. REBUILT THE PARK BRAKE. REPLACED SEALING RINGS AT THE DRIVE SHFATS THROUGH THE REAR HOUSING. PUT REAR HOUSING ON, WHEN ATTEMPTING TO SET REAR VALVE HOUSING ON, I NOTICED SOMETHING IN THE TRANSMISSION THAT STOOD OUT. USED A FLEXIBLE MAGNET & DREW OUT A BOLT THAT HAD BEEN FLOATING IN THERE FOR SOME TIME PER THE DAMAGE TO THE BOLT. REOPENED DTAC WITH BOLT SPEC SO THEY COULD POSSIBLY TELL WHERE THIS SIZE BOLT WAS USED. THIS SIZE IS NOT USED ANYWHERE IN THE TRANSMISSION. DISASSEMBLED TRANSMISSION. FOUND ONE BRIGHT SILVER BOLT. CHECKED & IT APPEARS THAT IT WAS THE RIGHT SIZE FOR WHERE IT WAS, HOWEVER IT DID NOT MATCH THE ONE THAT SHOULD BE THERE. IT IS BELIEVED THAT THERE WAS A MIX UP ON BOLTS IN THIS FLANGE & THIS BOLT FELL INTO THE TRANSMISSION DURING THE PROCESS. REASSEMBLED TRANSMISSION, PUT TRANSMISSION IN TRACTOR. REPLACED BROKEN SOLENOID AT LEFT SIDE OF TRANSMISSION. REPLACED ONE WIRE CONNECTOR FOR SOLENOID, IT WAS DAMAGED DURING THE SEPARATION. FASTENED & SECURED ALL LINES, DRIVE SHAFTS. TORQUED MOUNTING HARDWARE.



4121 North Highway 81 Bypass
 Enid, OK 73701
 Phone: (580) 237-2304
 www.pkequipment.com



JOHN DEERE

Invoice To Account No.:

Deliver To:

*** DOCUMENT COPY ***

SERVICE INVOICE

Internal Used Stock No. 196100	Internal Used Stock No. 196100	Invoice Number: 1455937
		Invoice Date: 1/31/2014
		Location: 2
Bus Phone:	Bus Phone:	Work Order Number: 318578
Prv Phone:	Prv Phone:	Payment Type: Account
		Page: 4 of 4

Make/Model:	JOHN DEERE JD 8360R
Meter Reading:	712
Serial Number:	1RW8360RPBD043281
Equipment Number:	104371

STARTED TRACTOR, PT1 630.13 WOULD LOCK THE MACHINE OUT. TESTED & HAD NOT SYSTEM 2 PRESSURE. CHECKED & HAD NO LUBE PRESSURE. AFTER SEVERAL TESTS & CHECKS & SEVERAL CALLS TO & FROM DTAC. I FOUND THAT THE C2 SOLENOID CLUTCH HAD A STUCK VALVE. REMOVED VALVE, CLEANED BORE & REASSEMBLED. STARTED TRACTOR, CODE CLEARED & TRANSMISSION CALIBRATED. CHECKED PRESSURES. CHECKED READINGS AT PT1 ADDRESSES FOR PARK PRESSURE, SYSTEM PRESSURE, LUBE PRESSURE, ALL ARE IN SPEC. DROVE TRACTOR & CHECKED, IN & OUT OF GEAR. PARK TO F-N-R. DROVE TRACTOR, NO CODES SET. I DROVE & CHECKED TRACTOR ON A FRIDAY AFTERNOON & THEN ON & ON MONDAY. ALL IS GOOD NOW.

TRACTOR WOULD NOT START GOOD ON INITIAL CHECKS. REPLACED BATTERIES DUE TO QUESTIONABLE VOLTAGE.

REPLACED TRANSMISSION OIL & FILTERS. 46 GALLONS OF BULK HYD FLUID.

Part Number	Description	Quantity	Unit Nett	Value	Taxed Ind
2490	SPLIT R/O	1.00	10,236.00	\$10,236.00	N

Labor: \$0.00 Parts: \$0.00 OL&M: \$0.00 Misc: \$10,236.00 Sub-Total: \$10,236.00

Customer PO No:	
Tax Exempt No:	731259841
Advisor:	Timothy Krienke

Labor:	\$405.00
Parts:	\$48.17
OL&M:	\$275.00
Misc:	\$10,243.50
Sales Tax:	\$0.00
Total:	<u>\$10,971.67</u>

TERMS AND CONDITIONS

Farm Plan transactions are subject to the terms of Farm Plan.
 All open accounts are payable by the 10th of the month following the date of purchase. Accounts not paid by the 10th of the month following purchase are subject to interest charges of 1.5% per month, which is an 18% annual rate. Accounts which are not paid by the 10th of the month are subject to closure and collection procedures. Parties agree that jurisdiction and venue of any action brought to enforce or collect this account shall properly lie in Kingfisher County, State of Oklahoma. In the event that P&K Equipment, Inc. must employ an attorney to enforce or collect this amount, they shall be entitled to recover reasonable attorney fees and expenses incurred therein.
 Purchaser certifies under penalty of perjury that he is engaged in farming or ranching and farm machinery & farm equipment parts described hereon will be used only in his farming or ranching operation.

Received by: Date:



4121 North Highway 81 Bypass
 Enid, OK 73701
 Phone: (580) 237-2304
 www.pkequipment.com



Invoice To Account No.:

Deliver To:

*** DOCUMENT COPY ***

SERVICE INVOICE

Internal Used Stock No. 196100

 Bus Phone:
 Prv Phone:

Internal Used Stock No. 196100

 Bus Phone:
 Prv Phone:

Invoice Number: **1703506**
 Invoice Date: 9/29/2014
 Location: 2
 Work Order Number: 383475
 Payment Type: Account

 Page: 1 of 2

Make/Model: JOHN DEERE JD 8360R
 Meter Reading: 725
 Serial Number: 1RW8360RPBD043281
 Equipment Number: 104371

Gen1- Internal
 COMPLAINT:
 SERVICE REQUEST:install return and power beyond

CAUSE:

CORRECTION: \$157.50
 DIAGNOSIS:

SERVICE QUOTE:

SERVICE PERFORMED: DROVE TO MACHINE INSTALLED POWER BEYOND ONTO MACHINE. KIT DID NOT COME WITH CASE DRAIN. WENT BACK TO SHOP & GOT FILLINGS FOR CHAIN & DROVE BACK TO TRACTOR & INSTALLED CASE DRAIN.

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>Unit Nett</u>	<u>Value</u>	<u>Taxed</u>	<u>Inc</u>
4120	SERVICE CALL FEE, ZONE 2	1.00	100.00	\$100.00	N	N
R218933	Cover	1.00	17.33	\$17.33	N	N
RE222718	Breakaway Coupler	1.00	142.07	\$142.07	N	N



4121 North Highway 81 Bypass
 Enid, OK 73701
 Phone: (580) 237-2304
 www.pkequipment.com



JOHN DEERE

Invoice To Account No.:

Deliver To:

*** DOCUMENT COPY ***

SERVICE INVOICE

Internal Used Stock No. 196100	Internal Used Stock No. 196100	Invoice Number: 1703506
		Invoice Date: 9/29/2014
		Location: 2
		Work Order Number: 383475
		Payment Type: Account
Bus Phone:	Bus Phone:	Page: 2 of 2
Prv Phone:	Prv Phone:	

Make/Model:	JOHN DEERE JD 8360R
Meter Reading:	725
Serial Number:	1RW8360RPBD043281
Equipment Number:	104371

Gen1- Internal RE248312	Adapter Fitting	1.00	46.07	\$46.07	N
----------------------------	-----------------	------	-------	---------	---

Labor: \$157.50 Parts: \$205.47 OL&M: \$0.00 Misc: \$100.00 Sub-Total: \$462.97

Customer PO No:	
Tax Exempt No:	731259841
Advisor:	SCOTT WARNOCK

Labor:	\$157.50
Parts:	\$205.47
OL&M:	\$0.00
Misc:	\$100.00
Sales Tax:	\$0.00
Total:	\$462.97

TERMS AND CONDITIONS

Farm Plan transactions are subject to the terms of Farm Plan.
 All open accounts are payable by the 10th of the month following the date of purchase. Accounts not paid by the 10th of the month following purchase are subject to interest charges of 1.5% per month, which is an 18% annual rate. Accounts which are not paid by the 10th of the month are subject to closure and collection procedures. Parties agree that jurisdiction and venue of any action brought to enforce or collect this account shall properly lie in Kingfisher County, State of Oklahoma. In the event that P&K Equipment, Inc. must employ an attorney to enforce or collect this amount, they shall be entitled to recover reasonable attorney fees and expenses incurred therein.
 Purchaser certifies under penalty of perjury that he is engaged in farming or ranching and farm machinery & farm equipment parts described hereon will be used only in his farming or ranching operation.

Received by: Date:



4121 North Highway 81 Bypass
 Enid, OK 73701
 Phone: (580) 237-2304
 www.pkequipment.com



JOHN DEERE

Invoice To Account No.:

Deliver To:

*** DOCUMENT COPY ***

SERVICE INVOICE

Internal Used Stock No. 196100

 Bus Phone:
 Prv Phone:

Internal Used Stock No. 196100

 Bus Phone:
 Prv Phone:

Invoice Number: **1722000**
 Invoice Date: 10/18/2014
 Location: 2
 Work Order Number: 383475
 Payment Type: Account

 Page: 1 of 2

Make/Model: JOHN DEERE JD 8360R
 Meter Reading: 725
 Serial Number: 1RW8360RPBD043281
 Equipment Number: 104371

Gen- Internal
 COMPLAINT:
 SERVICE REQUEST: get ready for rental

CAUSE:

CORRECTION:
 DIAGNOSIS:

\$141.67

SERVICE QUOTE:

SERVICE PERFORMED: JUMP STARTED TRACTOR. FILLED WITH 30 GALLONS DIESEL FUEL. SHOWED CUSTOMER HOW IVT TRANSMISSION WORKED.

NOTE: TRACTOR HAD A USED VEHICLE CONTROLLER ON CAB. TRANSMISSION WENT INTO CALIBRATION WHEN STARTED.

Part Number	Description	Quantity	Unit Nett	Value	Taxed Ind
9955	DIESEL	30.00	3.89	\$116.70	N

Labor: \$141.67 Parts: \$0.00 OL&M: \$0.00 Misc: \$116.70 Sub-Total: \$258.37

/PICK UP ONLY Internal
 COMPLAINT:
 PICK UP ONLY, NO DELIVERY

CAUSE:

CORRECTION:
 PICKED UP 8360R from Kent Wayman 10/1/14 (Rental return 816 hrs)

Part Number	Description	Quantity	Unit Nett	Value	Taxed Ind
-------------	-------------	----------	-----------	-------	-----------



4121 North Highway 81 Bypass
 Enid, OK 73701
 Phone: (580) 237-2304
 www.pkequipment.com



JOHN DEERE

Invoice To Account No.:

Deliver To:

*** DOCUMENT COPY ***

SERVICE INVOICE

Internal Used Stock No. 196100

 Bus Phone:
 Prv Phone:

Internal Used Stock No. 196100

 Bus Phone:
 Prv Phone:

Invoice Number: **1722000**
 Invoice Date: 10/18/2014
 Location: 2
 Work Order Number: 383475
 Payment Type: Account

 Page: 2 of 2

Make/Model: JOHN DEERE JD 8360R
 Meter Reading: 725
 Serial Number: 1RW8360RPBD043281
 Equipment Number: 104371

/PICK UP ONLY Internal 5220 40HP+ TRANSPORT FEE, ZONE 2 1.00 125.00 \$125.00 N

Labor: \$0.00 Parts: \$0.00 OL&M: \$0.00 Misc: \$125.00 Sub-Total: \$125.00

Customer PO No:
 Tax Exempt No: 731259841
 Advisor: SCOTT WARNOCK

Labor: \$141.67
 Parts: \$0.00
 OL&M: \$0.00
 Misc: \$241.70
 Sales Tax: \$0.00
 Total: \$383.37

TERMS AND CONDITIONS

Farm Plan transactions are subject to the terms of Farm Plan.

All open accounts are payable by the 10th of the month following the date of purchase. Accounts not paid by the 10th of the month following purchase are subject to interest charges of 1.5% per month, which is an 18% annual rate. Accounts which are not paid by the 10th of the month are subject to closure and collection procedures. Parties agree that jurisdiction and venue of any action brought to enforce or collect this account shall properly lie in Kingfisher County, State of Oklahoma. In the event that P&K Equipment, Inc. must employ an attorney to enforce or collect this amount, they shall be entitled to recover reasonable attorney fees and expenses incurred therein.

Purchaser certifies under penalty of perjury that he is engaged in farming or ranching and farm machinery & farm equipment parts described hereon will be used only in his farming or ranching operation.

Received by: Date:



4121 North Highway 81 Bypass
 Enid, OK 73701
 Phone: (580) 237-2304
 www.pkequipment.com



Invoice To Account No.:

Deliver To:

*** DOCUMENT COPY ***

SERVICE INVOICE

Internal Used Stock No. 196100	Internal Used Stock No. 196100	Invoice Number: 1735170
		Invoice Date: 10/31/2014
		Location: 2
		Work Order Number: 387117
		Payment Type: Account
Bus Phone:	Bus Phone:	Page: 1 of 2
Prv Phone:	Prv Phone:	

Make/Model:	JOHN DEERE JD 8360R
Meter Reading:	
Serial Number:	1RW8360RPBD043281
Equipment Number:	104371

Gen- Internal
 COMPLAINT:
 SERVICE REQUEST:A-1 inspection--it was having trans calibration codes

CAUSE:

CORRECTION:
 DIAGNOSIS:

\$810.00

SERVICE QUOTE:

SERVICE PERFORMED: PERFORMED CPO INSPECTION. CHANGED ALL FILTERS & ENGINE OIL. NO TRANS CAL
 CODES - TRANS CALIBRATED SEVERAL TIMES NO PROBLEMS.

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>Unit Nett</u>	<u>Value</u>	<u>Taxed Ind</u>
DKGA2019	Promotional Item	1.00	60.00	\$60.00	N
RE210102	AIR FILTER	1.00	102.61	\$102.61	N
RE210103	AIR FILTER	1.00	67.31	\$67.31	N
RE210857	OIL FILTER	2.00	80.09	\$160.18	N
RE284091	AIR FILTER	1.00	56.13	\$56.13	N
RE291412	AIR FILTER	1.00	56.13	\$56.13	N
RE509672	FILTER ELE	1.00	20.88	\$20.88	N
RE533910	FUEL FILTE	1.00	124.92	\$124.92	N
RE539465	Filter Element	1.00	85.44	\$85.44	N



4121 North Highway 81 Bypass
 Enid, OK 73701
 Phone: (580) 237-2304
 www.pkequipment.com



JOHN DEERE

Invoice To Account No.:

Deliver To:

*** DOCUMENT COPY ***

SERVICE INVOICE

Internal Used Stock No. 196100

 Bus Phone:
 Prv Phone:

Internal Used Stock No. 196100

 Bus Phone:
 Prv Phone:

Invoice Number: **1735170**
 Invoice Date: 10/31/2014
 Location: 2
 Work Order Number: 387117
 Payment Type: Account

 Page: 2 of 2

Make/Model: JOHN DEERE JD 8360R
 Meter Reading:
 Serial Number: 1RW8360RPBD043281
 Equipment Number: 104371

Gen- Internal Plus-50 II Oil 15W40 CJ4/SN 27.00 3.52 \$95.04 N
 TY26682

Labor: \$810.00 Parts: \$828.64 OL&M: \$0.00 Misc: \$0.00 Sub-Total: \$1,638.64

Miscellaneous Charges: Service Accessories \$40.97

Customer PO No:
 Tax Exempt No: 731259841
 Advisor: SCOTT WARNOCK

Labor: \$810.00
 Parts: \$828.64
 OL&M: \$0.00
 Misc: \$40.97
 Sales Tax: \$0.00
 Total: \$1,679.61

TERMS AND CONDITIONS

Farm Plan transactions are subject to the terms of Farm Plan.
 All open accounts are payable by the 10th of the month following the date of purchase. Accounts not paid by the 10th of the month following purchase are subject to interest charges of 1.5% per month, which is an 18% annual rate. Accounts which are not paid by the 10th of the month are subject to closure and collection procedures. Parties agree that jurisdiction and venue of any action brought to enforce or collect this account shall properly lie in Kingfisher County, State of Oklahoma. In the event that P&K Equipment, Inc. must employ an attorney to enforce or collect this amount, they shall be entitled to recover reasonable attorney fees and expenses incurred therein.
 Purchaser certifies under penalty of perjury that he is engaged in farming or ranching and farm machinery & farm equipment parts described hereon will be used only in his farming or ranching operation.

Received by: Date:



3802 W. Doolin Ave
 Blackwell, OK 74631
 Phone: (580) 363-3758
 www.pkequipment.com



Invoice To Account No.:

Deliver To:

*** DOCUMENT COPY ***

SERVICE INVOICE

Internal Used Stock No. 196100

 Bus Phone:
 Prv Phone:

Internal Used Stock No. 196100

 Bus Phone:
 Prv Phone:

Invoice Number: **1823221**
 Invoice Date: 4/1/2015
 Location: 10
 Work Order Number: 408546
 Payment Type: Account

 Page: 1 of 2

Make/Model: JOHN DEERE JD 8360R
 Meter Reading: 841
 Serial Number: 1RW8360RPBD043281
 Equipment Number: 104371

Gen- Internal
 COMPLAINT:
 SERVICE REQUEST: CHECK ALL FLUID LEVELS, ALL LIGHTS AND GAUGES, CHECK A/C FUNCTION

CORRECTION: \$113.25
 SERVICE REQUEST:

DIAGNOSIS:

SERVICE QUOTE:

SERVICE PERFORMED: check all lights, fluids and functions

Labor: \$113.25	Parts: \$0.00	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$113.25
-----------------	---------------	--------------	--------------	---------------------

/DELIVER ONLY Internal
 COMPLAINT:
 DELIVERY ONLY, NO PICK UP

CORRECTION:

Part Number	Description	Quantity	Unit Nett	Value	Taxed Ind
-------------	-------------	----------	-----------	-------	-----------



3802 W. Doolin Ave
 Blackwell, OK 74631
 Phone: (580) 363-3758
 www.pkequipment.com



JOHN DEERE

Invoice To Account No.:

Deliver To:

*** DOCUMENT COPY ***

SERVICE INVOICE

Internal Used Stock No. 196100

 Bus Phone:
 Prv Phone:

Internal Used Stock No. 196100

 Bus Phone:
 Prv Phone:

Invoice Number: **1823221**
 Invoice Date: 4/1/2015
 Location: 10
 Work Order Number: 408546
 Payment Type: Account

 Page: 2 of 2

Make/Model: JOHN DEERE JD 8360R
 Meter Reading: 841
 Serial Number: 1RW8360RPBD043281
 Equipment Number: 104371

/DELIVER ONLY Internal	40HP+ TRANSPORT FEE, ZONE 6	1.00	330.00	\$330.00	N
------------------------	-----------------------------	------	--------	----------	---

Labor: \$0.00 Parts: \$0.00 OL&M: \$0.00 Misc: \$330.00 Sub-Total: \$330.00

Miscellaneous Charges:
 Service Accessories \$11.08

Customer PO No:
 Tax Exempt No:
 Advisor: Cody Wornkey

Labor: \$113.25
 Parts: \$0.00
 OL&M: \$0.00
 Misc: \$341.08
 Sales Tax: \$0.00
 Total: \$454.33

TERMS AND CONDITIONS

Farm Plan transactions are subject to the terms of Farm Plan.
 All open accounts are payable by the 10th of the month following the date of purchase. Accounts not paid by the 10th of the month following purchase are subject to interest charges of 1.5% per month, which is an 18% annual rate. Accounts which are not paid by the 10th of the month are subject to closure and collection procedures. Parties agree that jurisdiction and venue of any action brought to enforce or collect this account shall properly lie in Kingfisher County, State of Oklahoma. In the event that P&K Equipment, Inc. must employ an attorney to enforce or collect this amount, they shall be entitled to recover reasonable attorney fees and expenses incurred therein.
 Purchaser certifies under penalty of perjury that he is engaged in farming or ranching and farm machinery & farm equipment parts described hereon will be used only in his farming or ranching operation.

Received by: Date:



4121 North Highway 81 Bypass
 Enid, OK 73701
 Phone: (580) 237-2304
 www.pkequipment.com



JOHN DEERE

Invoice To Account No.:

Deliver To:

*** DOCUMENT COPY ***

SERVICE INVOICE

Internal Used Stock No. 196100

 Bus Phone:
 Prv Phone:

Internal Used Stock No. 196100

 Bus Phone:
 Prv Phone:

Invoice Number: **1826614**
 Invoice Date: 4/4/2015
 Location: 2
 Work Order Number: 410242
 Payment Type: Account

 Page: 1 of 1

Make/Model: JOHN DEERE JD 8360R
 Meter Reading: 824
 Serial Number: 1RW8360RPBD043281
 Equipment Number: 104371

Gen1- Internal
 COMPLAINT:
 SERVICE REQUEST: INSPECT, MAKE AUCTION READY

CORRECTION: \$300.00
 SERVICE QUOTE:

SERVICE PERFORMED: Looked over for auction.

EXT WASH, EXT WAX, INT COMPLETE

Labor: \$50.00 Parts: \$0.00 OL&M: \$250.00 Misc: \$0.00 Sub-Total: \$300.00

Miscellaneous Charges:
 Service Accessories \$2.50

Customer PO No:
 Tax Exempt No:
 Advisor: Timothy Krienke

Labor: \$50.00
 Parts: \$0.00
 OL&M: \$250.00
 Misc: \$2.50
 Sales Tax: \$0.00
 Total: \$302.50

TERMS AND CONDITIONS

Farm Plan transactions are subject to the terms of Farm Plan.
 All open accounts are payable by the 10th of the month following the date of purchase. Accounts not paid by the 10th of the month following purchase are subject to interest charges of 1.5% per month, which is an 18% annual rate. Accounts which are not paid by the 10th of the month are subject to closure and collection procedures. Parties agree that jurisdiction and venue of any action brought to enforce or collect this account shall properly lie in Kingfisher County, State of Oklahoma. In the event that P&K Equipment, Inc. must employ an attorney to enforce or collect this amount, they shall be entitled to recover reasonable attorney fees and expenses incurred therein.
 Purchaser certifies under penalty of perjury that he is engaged in farming or ranching and farm machinery & farm equipment parts described hereon will be used only in his farming or ranching operation.

Received by: Date: